



Saab 900

RATING	SCORE
 ADULT OCCUPANT ★★☆☆☆☆	12 Front: 4 Side: 8
 PEDESTRIAN ★☆☆☆☆	N/A Pre 2002 rating

Adult occupant protection



Frontal impact driver



Frontal impact passenger



Side impact driver

- GOOD
- ADEQUATE
- MARGINAL
- WEAK
- POOR

Child restraints

18 month old Child	No information available
3 year old Child	No information available

Safety equipment

Front seatbelt pretensioners	<input checked="" type="checkbox"/>
Front seatbelt load limiters	<input type="checkbox"/>
Driver frontal airbag	<input checked="" type="checkbox"/>
Front passenger frontal airbag	<input checked="" type="checkbox"/>
Side body airbags	<input type="checkbox"/>
Side head airbags	<input type="checkbox"/>
Driver knee airbag	<input type="checkbox"/>

Pedestrian protection

No image car front available

Car details

Hand of drive	RHD
Tested model	Saab 900 2.0i
Body type	5 door hatchback
Year of publication	1997
Kerb weight	1315

Comments

The Saab 900 achieved a two-star front- and side-impact rating. The passenger compartment became structurally unstable and screen pillar movement was excessive following the frontal-impact test. Meanwhile, in the side-impact test, chest protection was assessed as poor. Furthermore, the presence of stiff structures in the area likely to be struck by the driver's knees during a frontal impact presented a significant risk of injury to his knees, thighs and pelvis.

Front impact

Front impact The driver's screen pillar was pushed backwards by 221mm (8.7in) and the passenger compartment lost structural stability. The driver's door was severely weakened at its hinges. The driver's door could not be opened by hand, even using extreme force, and tools had to be used. On opening the door, it became completely detached from the car. The passenger's door could be opened normally. The steering wheel moved rearwards by 167mm (6.6in) and upwards by 42mm (1.7in). There was moderate footwell intrusion and the brake pedal was pushed backwards by 193mm (7.6in). Although head protection in the test rated as 'good' the amount of steering wheel intrusion could have posed a greater risk to different-sized drivers or those in different seating positions, so was down-rated to 'adequate'. The driver's head contact on the airbag was stable. The restraint system kept the driver's chest away from the steering wheel, although forces transmitted to the chest via the seat belt presented some threat of injury. The intrusion into the cabin at facia level, together with the structural instability of the cabin, meant there was a more serious risk of chest injuries being sustained by

shorter or taller drivers and those in different seating positions. If the crash had occurred slightly differently, cabin intrusion could have been worse, and contributed to the likelihood of still further chest injuries. The driver's left knee brushed past the steering-column adjuster lever and just reached the fascia. However, a higher knee position at the moment of impact could have resulted in it striking the bolt for the steering column adjuster. The driver's right knee also hit the fascia, fracturing the plastic surface. If this contact had occurred in a slightly different horizontal position, the column mounting bracket would have been impacted. A slightly higher contact could have reached the column lock and adjuster mechanism and there was no energy-absorbing material present in this area. Had the knee penetrated slightly further, the steering column and its mounting bracket could have been hit. Protection for the right lower leg was rated as adequate, but only as marginal for the left lower leg. The degree of intrusion into the footwell resulted in foot and ankle protection earning a rating as 'weak'. Protection for the head, neck, and both legs was good, though forces transmitted via the seat belt to the chest presented some risk of injury. Protection for the feet and ankles was rated as good. The results for the passenger were not modified on the basis of structural damage to the car.

Side impact

Head protection was good, though the side of the car struck the driver's chest with sufficient force to pose a serious threat of life-threatening injury. The amount of force acting on his abdomen also indicated a threat of injury. Protection for the driver's pelvis was rated as 'adequate'.

Child occupant

The rear-facing seats in the Saab required supplementary straps. They were good in frontal crashes, but in the side-impact test they placed occupants close to the area of maximum car-body intrusion. The dummy ran a significant risk of head and chest injury. The recommended seats required reference to both the instruction leaflet and the car manual for fitting to be correct. The rear-facing child seats in the Saab featured a clear warning against using them in the front of any car where a passenger airbag is fitted and the car also displayed a warning label to that effect.

Pedestrian

Child head impact Four of the six test locations met proposed legislation: above the battery, over a bonnet strengthener, over the oil filler cap and above the corner of the rocker cover. One point performed better than average, one worse: at the join between bonnet and wing. Upper leg impact None of the three tests met proposed legislation. Two tests on the bonnet's front edge were better than average, one worse. Adult head impact None of the tests met proposed legislation. Four points were better than average: above a bonnet strengthener, over a wiper spindle, on a washer nozzle and on the scuttle panel. Two points were worse than average: above a suspension strut, and over a bonnet hinge. Leg impact None of the three tests met requirements. All three the bumper tests were better than average.