






Hyundai Tucson

RATING	SCORE	Front: 11.2	Side: 16	Pole: 2
 ADULT OCCUPANT ★★☆☆☆	29			
 CHILD OCCUPANT ★★☆☆☆	32			
 PEDESTRIAN ★☆☆☆☆	4			

Adult occupant protection



Frontal impact driver



Frontal impact passenger



Side impact driver

- GOOD
- ADEQUATE
- MARGINAL
- WEAK
- POOR

Child restraints

18 month old Child

Britax-Römer Baby-Safe Plus, rearward facing

3 year old Child

Britax-Römer Duo Plus Plus, forward facing

Pedestrian protection



Pedestrian protection

- GOOD
- ADEQUATE
- MARGINAL

Safety equipment

Front seatbelt pretensioners	<input checked="" type="checkbox"/>
Front seatbelt load limiters	<input checked="" type="checkbox"/>
Driver frontal airbag	<input checked="" type="checkbox"/>
Front passenger frontal airbag	<input checked="" type="checkbox"/>
Side body airbags	<input checked="" type="checkbox"/>
Side head airbags	<input checked="" type="checkbox"/>
Driver knee airbag	<input type="checkbox"/>
ISOfix front	<input type="checkbox"/>
ISOfix rear	<input checked="" type="checkbox"/>

Car details

Tested model	Hyundai Tucson 2.0VGT diesel, 4WD, LHD
Body type	5 door Translation not found
Year of publication	2006
Kerb weight	1760kg
VIN from which rating applies	From number 30000

Comments

Front impact

Structures in the dashboard represented potential hazards to the knees and femurs of the driver and passenger.

Side impact

The Tucson scored full points for its performance in the side impact and pole tests.

Child occupant

A rearward-facing child restraint should not be placed in the front passenger seat as the airbag for that seating position cannot be deactivated. Moreover, the label warning against using a rearward-facing childseat in that seating position did not meet Euro NCAP's requirements and did not score any points.

Pedestrian

The car scored no points for the protection offered to pedestrians by the bumper or the bonnet leading edge. The protection offered to a child pedestrian's head also scored no points.