



Skoda Fabia				
RATING	SCORE			
ADULT OCCUPANT ★★☆☆☆☆	32	Front: 12.9 Side: 15	Seatbelt reminder: 2 Pole: 2	
CHILD OCCUPANT ★★☆☆☆	36			
PEDESTRIAN ★☆☆☆	17			

Adult occupant protection







Frontal impact passenger




Side impact driver

Child restraints

18 month old Child	Fair BimboFix Type II ISOFIX, rearward facing
3 year old Child	Fair BimboFix Type II ISOFIX, forward facing

Pedestrian protection



Safety equipment

Front seatbelt pretensioners	$\mathbf{\underline{r}}$
Front seatbelt load limiters	
Driver frontal airbag	
Front passenger frontal airbag	
Side body airbags	
Side head airbags	
Driver knee airbag	

Car details

Tested model	Skoda Fabia, 1.2 Sport, LHD
Body type	5 door hatchback
Year of publication	2007
Kerb weight	1055kg
VIN from which rating applies	Applies to all applies Fabias

Comments

Front impact

The passenger compartment remained stable during the impact but structures in the dashboard presented a risk of injury to the knees and femurs of the driver and passenger.

Based on dummy results alone, the Fabia would have scored maximum points in the side impact and pole tests. However, in the side test, the rear door moved from the primary latch to the secondary latch position and the car lost one point available for that test.

Child occupant

The Fabia scored maximum points for its protection of the 18 month dummy in the frontal and side impact tests. In the side impact, the 3 year old's restraint rotated so that the dummy's head was not fully contained within the child seat, making it vulnerable to contact with parts of the car's interior. A switch is available to allow the front passenger's airbag to be disabled so that a rearwardfacing child restraint to be used in that seating position. However, information provided to the driver about the status of the airbag is not sufficiently clear. On cars not fitted with the switch, the airbag can be disabled by a dealer. There was inadequate warning of the dangers of using a rearward-facing child restraint in the front passenger's seat without first disabling the airbag. The presence of ISOFIX anchorages in the rear outboard seats was not clearly marked.

The bumper scored maximum points for the protection it offered to pedestrians' legs. However, the front edge of the bonnet scored no points.