

# Volvo V40

Volvo V40 1.6 diesel 'Kinetic', LHD







98%





ADULT OCCUPANT

88%



**PEDESTRIAN** 

SAFETY ASSIST

# Total 35 pts | 98%

CHILD OCCUPANT

### **ADULT OCCUPANT**



Driver

**SIDE IMPACT CAR** 

**SIDE IMPACT POLE** 

Passenger

### **HEAD**

**FRONTAL IMPACT** 

Driver airbag contact stable Passenger airbag contact stable

**CHEST** Passenger compartment stable Windscreen Pillar rearward 1mm Steering wheel rearward none Steering wheel upward none Chest contact with steering none wheel

**UPPER LEGS, KNEES AND PELVIS** 

Stiff structures in dashboard

Concentrated loads on knees

**LOWER LEGS AND FEET** 

Rearward pedal movement

Upward pedal movement

# 8 pts

### 8 pts



Car



Pole

3,5 pts

### SIDE IMPACT

Footwell Collapse

Head protection airbag	Yes
Chest protection airbag	Yes

none

none

accelerator - 19mm

brake - 15mm

#### **WHIPLASH**

Seat description	Standard textile, 6 way manual
Head restraint type	Passive
Geometric assessment	1 pts
TESTS	
- High severity	1,6 pts
- Medium severity	2,9 pts
- Low severity	3 pts

## **REAR IMPACT (WHIPLASH)**

GOOD
ADEQUAT
MARGINAI



**POOR** 



### **CHILD OCCUPANT**

## Total 37 pts | 75%

#### **18 MONTH OLD CHILD**

Restraint Volvo Child Restraint

Group 0, 1
Facing rearward
Installation Adult seatbelt



PERFORMANCE 8 pts

INSTRUCTIONS 4 pts

INSTALLATION 2 pts

#### **FRONTAL IMPACT**

Head forward movement	protected
Head acceleration	good
Chest load	fair

#### **SIDE IMPACT**

Head containment	protected
Head acceleration	good

#### **3 YEAR OLD CHILD**

Restraint Volvo Child Restraint

Group 0, 1
Facing rearward
Installation Adult seatbelt



PERFORMANCE 9,6 pts

INSTRUCTIONS 4 pts

INSTALLATION 2 pts

#### **FRONTAL IMPACT**

Head forward movement	protected
Head acceleration	good
Chest load	fair

#### **SIDE IMPACT**

Head containment	protected
Head acceleration	fair

VEHICLE BASED ASSESSMENT

7 pts


Airbag warning Label

Test and pictogram label permanently attached to both sides of the passenger sun visor

### **PEDESTRIAN**

Total 32 pts | 88%

# SAFETY ASSIST Total 7 pts | 100%



HEAD	24 pts
PELVIS	2 pts
LEG	5,8 pts

1 pts
Pass
3 pts
Pass
1,04 %
1,38 %
3,12 m

SEATBELT REMINDE	R 3 pts
- driver	Pass
- passenger	Pass
- rear	Pass



### **DETAILS OF TESTED CAR**

#### **SPECIFICATIONS**

**Tested model** Volvo V40 1.6 diesel 'Kinetic', LHD

**Body type** 5 door estate

Year of publication 2012 Kerb weight 1377kg

VIN from which rating applies applies to all V40s of the

specification tested

#### SAFETY EQUIPMENT

Front seatbelt pretensioners

Front seatbelt load limiters

Driver frontal airbag

Front passenger frontal airbag

Side body airbags

Side head airbags

Driver knee airbag

Speed Limitation Assistance

**Electronic Stability Control** 

Seatbelt Reminder driver, passenger

and rear

active

#### COMMENTS

#### Adult occupant

The passenger compartment remained stable in the frontal impact. Dummy readings in the frontal test indicated good protection of the knees and femurs of the front seat occupants. Volvo showed that a similar level of protection would be provided for occupants of different sizes and to those sat in different positions. In the side barrier impact, good protection was provided to all body areas and the car scored maximum points. Even in the more severe side pole test, maximum points were scored. The seat and head restraint provided good protection against whiplash injury in the event of a rear-end collision.

#### **Child occupant**

Both child dummies were sat in rearward-facing, Volvo-branded child restraints. In the side impact, both dummies were properly contained by the shells of their restraints, minimising the risk of contact with parts of the car interior. The passenger airbag can be disabled by a Volvo dealer to allow a rearward-facing restraint to be used in that seating position. The dangers of using a rearward-facing restraint in the passenger seat without first disabling the airbag are clearly explained in the car.

#### **Pedestrian**

The V40 is equipped with an under-bonnet airbag system. This detects when a pedestrian has been struck and lifts the bonnet to provide greater protection to the head. The airbag also covers the windscreen pillars to provide better protection in those areas. Volvo demonstrated that the system would operate over a range of speeds and would detect different pedestrian statures. The system worked well, the bonnet offering good protection in all areas likely to be struck by a pedestrian's head, and scoring maximum points in this area. The front edge of the bonnet did provided poor protection in most areas tested while the bumper was predominantly good.

#### Safety assist

Electronic stability control is standard equipment on the V40 and met Euro NCAP's test requirements. A driver-set speed limitation device is also standard and was rewarded. A seatbelt reminder system is standard for the driver, passenger and rear seats.